

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No 128008

RECEIVED FROM: Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080107-5

| | | | | | |
|----------------------------------------------------|-----------------------|-----------------------|---------------------------------------|-------------------------------|-----------|
| DATE REC'D 1-14-57 | | P. O. NO. 6076 | | VENDOR PACKING SLIP NO. 14931 | |
| CHARGE TO | CONTRACT CODE NO. 322 | DRAWING NUMBER 000000 | DWG. DASH OR STANDARD PART NO. 10197 | DWG. REV. 0 | LOT NO. 0 |
| QUANTITY RECEIVED | CLASS NUMBER 00 | OPER NUMBER 00 | BUY OUT CODE NO. 02 | ACCT. OR W. O. NO. S. O. NO. | |
| DRAWING NO. AND DESCRIPTION | | | QUANTITY | | |
| 100 720180-3 RELAY NOTE PLATE LOCK 5/8 B.U. 1/2-20 | | | 100 | | |
| RECEIVED BY [Signature] | | | INSPECTED BY [Signature] DATE 1/14/57 | | |
| REJECTS RETURNED ON SHIP MEMO NO. | | | | | |

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No 128021

| | | | | | |
|---------------------------------------------|-----------------------|-----------------------|---------------------------------------|------------------------------|-----------|
| DATE REC'D 1-16-57 | | P. O. NO. 6094 | | VENDOR PACKING SLIP NO. 494 | |
| CHARGE TO | CONTRACT CODE NO. 322 | DRAWING NUMBER 000000 | DWG. DASH OR STANDARD PART NO. 3.673 | DWG. REV. 0 | LOT NO. 0 |
| QUANTITY RECEIVED | CLASS NUMBER 00 | OPER NUMBER 00 | BUY OUT CODE NO. 02 | ACCT. OR W. O. NO. S. O. NO. | |
| DRAWING NO. AND DESCRIPTION | | | QUANTITY | | |
| 5 720124-21 RELAY 2A500000 556 BOMI-SEALING | | | 5 | | |
| RECEIVED BY [Signature] | | | INSPECTED BY [Signature] DATE 1/14/57 | | |
| REJECTS RETURNED ON SHIP MEMO NO. | | | | | |

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080107-5